



VeriMark Desktop Windows 10 Manual Driver Install

Install the driver through Windows 10 Manual driver install


1. On the VeriMark support page, select **VeriMark Desktop** to go to the setup guides and driver download.




2. Download the driver from the VeriMark Desktop support page by clicking on the "Manual driver install button".




3. The compressed folder will be downloaded to your specified location.




4. Extract the files of the compressed folder to a selected destination.




5. A folder with the extracted files will be created.




6. Go to **Device Manager** and right click on the unknown device and select **Update driver**.




7. Click on "Browse my computer for drivers".




8. Select **Browse** to select a folder on your machine.




9. Choose the extracted folder location on Step 4.




10. Click **Next** to install the driver.



11. Driver install will take a couple of minutes.



12. Once **successfully installed** click close.



13. Kensington fingerprint key will show on device manager.

