


Kensington takes pride in making our comprehensive installation guides easy to follow with simple illustrations and step-by-step instructions. This guide will walk you through setup and help you get to know your VeriMark™ Desktop.




Please update operating system (Windows 10) before setting up VeriMark™ Desktop. If using an online service for WebAuthn make sure you use the latest browser version (Edge, Chrome, Safari and Firefox.)

### VeriMark™ Desktop Microsoft Edge Setup Guide


1. Select your account icon then click **Sign in** to login your Microsoft account



2. Choose your account then click **Continue** button




3. Key in your email and password of Microsoft account




4. Select your account icon on the top right side of Edge, then click **Manage profile settings**




5. Select **Profiles** then click **Manage account** item




6. Key in your email address and password then click **Next**




7. Select **Security** icon




8. Click **More security options** icon




9. Select **Set up Windows Hello** item




10. Insert your fingerprint device into PC then select **Next** button




11. Touch your security key with your enrolled finger



12. Setup the name of your fingerprint device, then click **Next**




13. Fingerprint device setup has completed, click **Got it** button




### How to Remove Security Key from Your Account

1. **Sign in** your Microsoft account


2. Select **Security** icon




3. Click **More security options** icon



4. Click **Manage your sign-in methods** item



5. Select **Remove** button



6. Click **Remove** button